Inspection Report

By Sri.K. Manjunath
Retd. Executive Engineer

Name of Work: Repairs to Buildings at Dasarahalli Sub Division Ward No.14 Bagalagunte, T.Dasarahalli Sub Division.

B.R.No: 690 /17-18 28/03/2017

Estimate Cost: 1-00 Lakhs

Bill Amount: Rs 98,773/-

Date of Inspection 22/06/2017

Observation and Conclusion:

The above said work "Repairs to Buildings at Dasarahalli Sub Div ward no 14 Bagalagunte, T. Dasarahalli Sub Div" was shown to me by the Concerned ward Engineer

The above said work is inspected by me along with the Concerned ward Engineer

The work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Repairs to Buildings at Dasarahalli Sub Division Ward No.14 Bagalagunte, T.Dasarahalli Sub Division.

BR No. 690 , Date. 28/03/2017

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT